


# FLASH REPORT


GOLDEN STAR (BOGOSO/ PRESTEA) LTD

<u>Report number</u> <b>007</b>	<u>Date of incident:</u> <b>13/11/2009</b>	<u>Time of incident:</u> <b>10:45hrs</b>
<b>INJURY</b>	<b>PROPERTY DAMAGE/LOSS</b>	<b>ENVIRONMENTAL</b>
<b>SECURITY</b>	<b>NEAR MISS</b>	
<u>Department Manager</u>	<u>Department</u> <b>Mine Maintenance</b>	<u>Supervisor</u>
<u>Nature and type of Injury/Illness</u> <b>Traumatic Amputation Right Arm</b>	<u>Equipment Type / No.</u> <b>EX10</b>	<u>Incident Location</u> <b>Buesichem Pit Collar</b>
<u>Person involved</u>	<u>Company ID</u>	<u>Name of witness</u>
<u>Injury Classification:</u> <b>MAJOR</b> MINOR                  NEAR MISS		
<u>Loss Classification:</u> Electrical/power outage   -   Fire   -   Equipment failure   -   Explosion		
<u>Estimated Cost of Impact:</u>		
<b>DETAILED DESCRIPTION OF INCIDENT</b>	EX10 cylinder was taken out and secured on a wooden block on top of the stick for the welder to take off the bushings. The first bushing was taken off and just as the second was being washed, the cylinder came off the wooden block, dropping on the right arm of the welder. He suffered a traumatic amputation and rushed to the site clinic.	
<b>ROOT CAUSES OF INCIDENT</b> <small>(Similar to ICAT investigation criteria)</small>	Under investigation	
<b>IMMEDIATE ACTIONS TO PREVENT RE-OCCURRENCE:</b> <small>(TO BE COMPLETED BY MANAGEMENT )</small>		
<b>DEVIATIONS FROM OUR H &amp; S STANDARDS / PROCEDURES</b>		



The first bushing that was taken off

A close shot of the cylinder edge which trapped injured.



The cylinder edge which trapped injured.

