

EQUIPMENT SAFETY ALERT

MODEL INVOLVED:

Caterpillar D10T TRACK-TYPE TRACTORS (Dozer)

A potential for chafing has been identified on the product listed above with the 265-3955 Fuel Line and the 213-7009 Alternator Cable on the left side of the engine and the 265-3965 Fuel Line and the engine harness assembly on the right side of the engine. These chafing points could cause premature failure of the fuel lines and result in a fire with the potential for injury or death.

Contact your local Caterpillar dealer immediately to schedule service. The dealer will advise you of the time required to complete this service. Please refer the dealer to their service letter dated June 17, 2005 when scheduling this service. You will not be charged for the service performed.

