

2013 KCA Pre-shift contest

Fireboss Station	Rule #
Start Clock	1
Check in	1
Check out	1
Stop clock	1
Check detectors	19
Check SCSR	3
All required equipment	2
# 1 Entry	
Visual roof & rib	10
Gas test at belt	5
DTI at belt	4
Air reading at AMS	7
Correct backward directional cone	12
Check mine phone	19
Clean coal spill	12
Check B x-cut test hole	10
Check C x-cut test hole	10
Gas test at last row of bolts	5
DTI at last row of bolts	4
Danger last row 5' from face	11

#2 entry	Rule
Visual roof & rib	10
Gas test travelway	5
DTI travelway	4
Check test hole B x-cut	10
Gas test powercenter	5
DTI powercenter	4
Gas test scoop charger	5
DTI scoop charger	4
Knock power on scoop charger/ tag out	12
Disconnect scoop batteries (verbally)	12
Use sledge to make regulator	12
Check regulator airflow	7
Install fire extinguisher at charger	12
Danger no test hole C x-cut	11
Correct line curtain	12
Gas test at face	5
DTI at face	4
Danger tag at last row of bolts	11
Pull loose rib C x-cut 2/3	12
Air reading C x-cut 2/3	7

#3 Entry	Rule
Visual Roof & Rib	10
Danger not bolted	11
Danger deep cut	11
Danger unbolted over 24 hours	11
Gas test at last row of bolts	5
DTI at last row of bolts	4
Hang line curtain	12
Check test hole C x-cut	10
Check test hole B x-cut	10
Gas test at roof bolt supplies	5
DTI at roof bolt supplies	4