





Solution Map

GAS PLACARD KEY	
	= Clear air
	= 17 % O ₂ CO - 1300 ppm CH ₄ - 0% Light Smoke
	= 15 % O ₂ CO - 4000 ppm CH ₄ - 0% Heavy Smoke



Ventilation Change #1

- Maintain air lock doors closed
- Close ventilation door in V Access #1
- Maintain Temp. Stopping in Entry #3
- Line Brattice in Entry #2

Air Lock Door (Closed)

Close Ventilation Door

V Access #1

X-Cut #2

X-Cut #1

Line Brattice

S

B

D

D

Entry 1

Entry 2


Entry 3

Entry 1


Entry 2

Entry 3


X-Cut #2



X-Cut #1



V Access #1



Judge Map
Team Name: _____
Team No.: _____