



PAMAPERSADA NUSANTARA

ACCIDENT NOTIFICATION - POTENTIAL FATALITY

(Preliminary Information)

DATE/Tanggal:	September 23 rd 2007
TIME/Jam:	14.40 Wita
Location/Lokasi:	Pelikan Pit Panel 5
IMMEDIATE SUPERVISOR (s):	-
COMPANY (S): Perusahaan	PT. PAMAPERSADA NUSANTARA
DEPARTMENT(S)	Prod Department
BRIEF DESCRIPTION: Penjelasan singkat kejadian	<p>Pukul 14.40 Light Vehicle #PMB15 dengan 1 pengemudi dan 2 orang penumpang menuju area drilling Panel 5, saat sampai di ramp Panel 5, LV#PMB15 terserempet lalu terseret oleh HD785 # DT3047.</p> <p>Dari 3 penumpang LV # PMB 15 (pengemudi dan dua orang penumpang), setelah di lakukan penanganan di Medika Plaza, dua orang mengalami cedera ringan dan diperbolehkan pulang, sementara satu orang masih dalam observasi dokter karena diduga ada cedera di tulang duduk.</p> <p><i>At 02.40 PM a light vehicle (PMB15) with one driver and two passengers was traveling to Panel 5 drilling area, when arrived at Panel 5 ramp, it was caught & dragged by a HD785 (DT3047).</i></p> <p><i>Of the three passengers of PMB15 (driver and two passengers), after treated and observed at Medika Plaza, two had minor injuries and released while one passenger was still under observation and suspected to have close fracture on left pelvic (ischium).</i></p>
ESTIMATED LOSS: Perkiraan Kerugian	Being Investigated / Sedang diinvestigasi
PROBABLE IMMEDIATE CAUSES:	Being Investigated / Sedang diinvestigasi
PROBABLE BASIC CAUSES:	Being Investigated / Sedang diinvestigasi

Pictures / gambar:

