

# Important Safety Recall

## Michigan Ladder Certain Type IA, Type I and Type II “D” Rung Fiberglass Extension Ladders

The fly section on the ladder may bind without locking.

The following Michigan ladders are affected:

**386124      386128      386132      386136      386140**

(On the ladder, the “XX” will identify a particular model size).

**Only ladders with manufacture dates/date codes  
September 2007 and October 2007 are affected.**

The model number can be located on the model number label on the left side rail of the ladder.



### Michigan Ladder Label Location:

- Left hand side rail
- Model Number above OSHA stamp



- Date of Manufacture is punched out on separate label under bar code.

Ladders manufactured during September 2007 and October 2007 but with two green dots near the bottom of the left side base rail have already been inspected or repaired and are not affected.



If your ladder is affected, STOP USING IT IMMEDIATELY, and call Louisville Ladder toll free at **1-800-660-4356**

between 8:00 a.m. and 5:00 p.m., Eastern Time, Monday through Friday, or at [www.louisvilleadder.com](http://www.louisvilleadder.com) for information on how to inspect and receive compensation if necessary.