

2016 KENTUCKY RIVER PRE-SHIFT CONTEST

STATEMENT

YOU ARE THE PRE-SHIFT EXAMINER FOR THE HAZ COAL COMPANY, NUMBER 1 MINE.


YOU ARE WORKING ON THE 001 SECTION WHEN THE STACKER BELT BROKE.

THE CREW HAS BEEN INSTRUCTED TO TRAVEL TO THE #3 LEFT PANEL TO RETRIEVE BELT STRUCTURE, BELT, WATER LINE, HIGH VOLTAGE CABLE FTC

YOU HAVE BEEN SELECTED TO DO A SUPPLEMENTAL EXAMINATION OF THE AREA.

YOU ARE TO EXAMINE THE AREA ON THE MAP PROVIDED.


THE VENTILATION REQUIREMENT IS THAT AIR WILL BE ENTERING ALL 3 ENTRIES AND STOPPINGS ARE NOT REQUIRED TO BE INSTALLED BETWEEN ENTRIES.



#1 entry		#2 entry		#3 entry
		ŀ		j
ſ		ſ		l
		ì		į į
Ì				1
		į		
_		_		
		_		
1				
	•			
•				
				ļ.
	· · · · · · · · · · · · · · · · · · ·	. ,		,
		j		J
		1 1		7
	,			Į l
		J		,
				1
]]
		1	1	

PRE-SHIFT EXAMINATION CONTEST JUDGES DISCOUNT SHEET

CONTESTANT	NO	* DENC	LES DE	SCOUNT
	OUTSIDE	WEG	NO	DIUE
(1) CUTCK DI		<u>YES</u>	<u>NO</u> *	RULE 1
(1) CHECK IN			*	3
(2) CHECK SCSR	rop.		 *	19
(3) CHECK METHANE/OXYGEN DETECT	IOR		*	1
(4) CHECK OUT			*	2
(5) HAVE ALL REQUIRED EQUIPMENT			*	14
(6) EQUIPMENT MAINTAINED IN OPERABLE CONDITION				1-1
OPERABLE CONDITION	NO. 3 ENTRY			
		<u>YES</u>	<u>NO</u>	RULE
(1) DTI THE #3 ENTRY			*	4
(2) TAKE GAS TEST IN THE #3 ENTRY			 *	5
(3) TAKE A PROPER GAS TEST			*	6
(4) VERBALLY STATE ROOF AND RIBS			_*	10
(5) DANGER DRAW ROCK			*	11
(6) DTI DANGER AT ROOF FALL			*	4
(7) ENDANGER SELF IN DRAW ROCK		*		16
(8) DANGER FLOAT COAL DUST			*	11
(9) DTI DANGER AT FLOAT COAL DUS'	Γ		*	4
	NO. 2 ENTRY			
		<u>YES</u>	NO .	RULE
(1) DTI THE #2 ENTRY			 *	4
(2) TAKE GAS TEST IN THE #2 ENTRY			 *	5
(3) TAKE A PROPER GAS TEST	•		*	6
(4) VERBALLY STATE ROOF AND RIBS			— .	10
(5) DANGER LOOSE RIB				11
(6) DTI DANGER AT LOOSE RIB		—	 *	4
(7) ENDANGER SELF IN LOOSE RIB		— *		16
(8) DANGER ROOF FALL		* *	 :	11
(9) DTI DANGER AT ROOF FALL		*	— *	4
(10) ENDANGER SELF IN ROOF FALL	NO. 1 ENTRY	<u> </u>		16
	NO. I ENTRI	YES.	<u>NO</u>	RULE
(1) DTI THE #1 ENTRY		124	*	4
(2) TAKE GAS TEST IN THE #1 ENTRY			 *	5
(3) TAKE A PROPER GAS TEST			 *	6
(4) VERBALLY STATE ROOF AND RIBS			<u></u> *	10
(5) DANGER ROOF FALL			*	11
(6) DTI DANGER AT ROOF FALL			*	4
(7) ENDANGER SELF IN ROOF FALL		*		16
(8) PUMP WATER			*	12
(9) VENTILATE EXPLOSIVE MIXTURE		_* 	*	12
(10) RETEST AFTER VENTILATION			*	5
(11) VENTILATE #1 ENTRY	•		*	11
(12) ENDANGER SELF IN WATER		*		16
	GENERAL RULES			
		YES	<u>NO</u>	RULE
(1) DID CONTESTANT RUN		*	 .	13
(2) EXAM ALL ACCESSIBLE AREAS			 *	18
(3) COMPLY WITH GENERAL RULES			*	19



Use Indelible Pencil or Ink	PRESH	IFT - CERTIFIED E	XAM	<u>INER'S REPOI</u>	<u>RT</u> r	eport Shall Be	Signed When Finishe
Date of Examination:06-14-16		Time From	Time From:		M/PM To: AM/PM		I/PM
Section/Area:#3 Left	Panel	R	Reporte	d Outside? Yes	No	Time:	AM/PM
Reported By:	Pre-shift requir	Receive	d By: _ or to a	nyone working i	(A) n the area.	<u>(INIT</u> UTHORIZE	<u>CIAL)</u> D PERSON)
Location	Hazardous Condition		Action Taken			CH4	
#1 Return Entry	Water roofed 5.3% methane No air movement		Pumped Ventilated Ventilated			0.0%	
#2 Intake Entry	Unsafe rib			Dangered			0.6%
#3 Intake Entry	Draw rock			Dangered			0.1%
Crosscut between 1 and 2	Roof fall in	crosscut		Dangered			
				<u> </u>			
	··	Air Measur	ements				
Location		CFM		Locati	ion		CFM
,							
*LOCC *Longwall Intak	e Entry(ies)	*Intake End Pillar Line		OCC Where Equ	ipment Beir	g Installed o	or Removed
Longwall Headgate :Remarks:		Velocit 		wall Tailgate:			
SIGNATURE		06-1	14-16_				
Signed by Preshift Certified Ex	aminer	_	Date			Certification	on Number

Certification Number

Countersigned by Operator/Agent

THIS RECORD TO BE MAINTAINED FOR ONE (1) YEAR

Date

Kentucky River Mine Rescue Contest June 14-16, 2016

Preshift Working Order

Working Order	Company Name Team Name	Contestant
1	Alden Resources LLC Mine Rescue Services Blue Team	Rick Thomas
2	Alpha Natural Resources South West Regional	Charles Conn
3	Arch Coal - Lone Mountain Processing Inc Lone Mountain Team	Joe Eldridge
4	Arch Coal - Lone Mountain Processing Inc Lone Mountain Team	John Rutherford
5	Drummond Company Inc Shoal Creek Red Team	David Crowe
6	Maxxim Shared Services Blue Team	Billy Sluss
7	Maxxim Shared Services Blue Team	Casey Mooneyhan
8	Revelation Energy LLC Revelation Energy Mine Rescue Blue Team	Jeremy Oliver

_	Written Examination Pre	•
C	ontestant Name	Ieam number
1.	When taking a reading with an anemo traverse the (MSHA 3028 A area B airway C entry	•
2.	The end of permanent roof support shawarning, or a physical barrier shall be permanent support. (30 CFR 75.208) A stop B impede C prevent	<u> </u>
3.	Ventilation controls are used underground of the mine. (MSHA 302 A areas B sections C airways	
4.	Tests for oxygen deficiency shall be made approved oxygen detectors maintained condition. (30 CFR 75.320(b)) A certified B qualified C trained	
5.	Lubricating oil and grease closed metal containers. (30 CFR 75.110 A used B kept C stored	_underground shall be stored in fireproof, 04).
6.	Before implementing an approved rev who are affected by the revision shall l 75.220(d)) A trained B instructed	ision to a roof control plan, all persons pein its provisions. (30 CFR

,

7.	Self-contained self-rescuers are used to protect the wearer from the effects of irrespirable A air B atmosphere C conditions
8.	Any area of the mine where a hazardous condition isshall be posted with a conspicuous danger sign where anyone entering the area would pass. (30 CFR 75.363(a)) A found B observed C encountered
9.	A sightline or other method of directional control shall be used to maintain the projected direction of mining in entries, rooms, crosscuts and pillar (30 CFR 75.203(b)) A cuts B splits C recovery
10.	After each time a self-rescue device is worn or carried, the device shall be inspected for damage and for the integrity of its seal by aperson. (30 CFR 1714-3(b). A trained B qualified C certified

Written Examination Pre-shift Kentucky River Answer Key

1.	В	airway
2.	В	impede
3.	В	sections
4.	В	qualified
5.	В	kept

6. B instructed7. B atmosphere

8. B observed

9. B splits 10. A trained