

4 missing


MAPS up to date

Exhausted FAN Running

Bring All missing persons to FAB

Exhausted FAN must stay Running

NO REVERSE





4.1% CH₄
3 ppm CO
6 ppm NO₂
19.5% O₂

UNCONSCIOUS
LIVE MAN

5.1% CH₄
1 ppm CO
1 ppm NO₂
19.5%

5.1% CH₄
3 ppm CO
2 ppm NO₂
19.5% O₂





4.1% CH₄
 3 ppm CO
 6 ppm NO₂
 19.5% O₂

UNCONSCIOUS
 Live man

5.1% CH₄
 1 ppm CO
 1 ppm NO₂
 19.5%


5.1% CH₄
 3 ppm CO
 2 ppm NO₂
 19.5% O₂

1.1% CH₄
 7 ppm CO
 1 ppm NO₂
 19.5% O₂

5.2% CH₄
 2 ppm CO
 2 ppm NO₂
 19.6% O₂

5.1% CH₄
 0 ppm CO
 1 ppm NO₂
 19.6% O₂

5.4% CH₄
 3 ppm CO
 1 ppm NO₂
 17.9% O₂



4.1% CH₄
 3 ppm CO
 6 ppm NO₂
 19.5% O₂

UNCONSCIOUS
 Live man


5.1% CH₄
 1 ppm CO
 1 ppm NO₂
 19.5% O₂


5.1% CH₄
 3 ppm CO
 2 ppm NO₂
 19.5% O₂

2ND
 VENT

1.1% CH₄
 7 ppm CO
 1 ppm NO₂
 19.5% O₂

5.2% CH₄
 2 ppm CO
 2 ppm NO₂
 19.6% O₂

















4.1% CH₄
3 ppm CO
6 ppm NO₂
19.5% O₂

UNCONSCIOUS LIVE MAN

5.1% CH₄
1 ppm CO
1 ppm NO₂
19.5%


5.1% CH₄
3 ppm CO
2 ppm NO₂
19.5% O₂

Intake
AIRSHaft



X' (BC)

1x1 (2E)



XXXXX
XXXXX



